

Technical Info

Information on formic acid

Recommended storage conditions:

May decompose forming gaseous products, especially when stored over long periods.

Close vessels such that the internal pressure can escape (e.g. overpressure protection).

Store in a dry place that is protected from light and well-ventilated. Keep away from heat and ignition sources. Keep under lock and key or only accessible to competent personnel or their agents.

Please replace the transport cap with the degasing cap included when stored.

Packages with degasing cap must be stored beneath a vent or in a well-ventilated storage location.

The transport of formic acid packages with degasing cap is not permitted.